ECS Configuration (nange Request				Page 1 of	Paç	ge(s)	
1. Originator	2. Log Date:	3. CCR #:		4. Rev:	5. Tel:	6. Rm #:	7. Dept.	
Robert Cole	02/15/02	02-0134			301-925-0799	2110C	SE/HW	
8. CCR Title: Update EDC disk configs and Hardware Diagram								
9. Originator Signature/Date					11. Type:	12. Need Date: 2/28/02		
Robert Cole /s/ 02/15/02			ll C		CCR			
13. Office Manager Signature/Date			14. Category of Ch Update ECS Basel		_	15. Priority: (If "Emergency" fill in Block 27). Routine		
<u> </u>			17. Schedule Impact:		18. CI(s) Affected:			
						21. Estimated Cost:		
N/A					None - Under 10	00K		
22. Source Reference: ☐ NCR (attach) ☐ Action Item ☐ Tech Ref. ☐ GSFC ☒ Other: M&O audit deficiency report # 0534								
23. Problem: (use additional Sheets if necessary) The recent PCA audit of NSIDC discovered discrepancies between the hardware diagrams and disk configs at NSIDC. This prompted further checking of these documents at other DAACs and discrepancies between the disk config diagrams and hardware diagram were noted.								
24. Proposed Solution: (use additional sheets if necessary) Baseline the attached updates to the EDC hardware diagram and disk configs								
25. Alternate Solution: (use additional sheets if necessary)								
26. Consequences if Change(s) are not approved: (use additional sheets if necessary)								
27. Justification for Emergency (If Block 15 is "Emergency"):								
28. Site(s) Affected: ☐ EDF ☐ PVC ☐ VATC ☒ EDC ☐ GSFC ☐ LaRC ☐ NSIDC ☐ SMC ☐ AK ☐ JPL ☐ EOC ☐ IDG Test Cell ☐ Other							JPL	
29. Board Comments:				30. V	Work Assigned To	o: 31. CCR C	Closed Date:	
32. EDF/SCDV CCB Chair (S	Sign/Date): D	visposition: Ap	proved	App/Co	m. Disapproved	Withdraw Fwo	/ESDIS ERB	
Fwd/ECS								
33. M&O CCB Chair (Sign/I Gary Gavigan /s/ 02/19/	-	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB						

Fwd/ECS

34. ECS CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fw	vd/ESDIS ERB
	Fwd/ESDIS	